

PACKAGING SPECIFICATION (包裝作業規範)

SPEC.NO.(規範編號)		Q4976SPP-1406		PAGE		1/4		REV.		A	
APPLICABLE CUSTOMER (適用客戶)	ALL	APPLICABLE PRODUCT (適用產品)	4976-F2X _{xx} THB-2X20CM-A _{xx}			PACKAGING CATEGORY (包裝方式)		PE BAG PACKING			

[illegible]

DIVISION (事業單位)	Product Development (產品開發課)	APPROVED (核 准)	CHECKED (審 核)	PREPARED (制 表)	Ping 2025/05/19
--------------------	----------------------------------	-------------------	------------------	-------------------	-----------------

歐品電子(昆山)有限公司

OUPIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)



CONFIDENTIAL TOP SECRET

SPEC.NO.(規範編號) Q4976SPP-1406

PAGE 2/4 REV. A

PACKING OPERATION DIAGRAM & INSTRUCTION (包裝作業圖示及說明)

REMARK (備 注)



Paper Box : CT-0.5
(紙箱 : CT-0.5)

一.Packing Mode: (包裝方式)

(1).PE bag A3364 , CT-0.5paper box, drying agent.
(PE袋 A3364 , CT-0.5紙盒,干燥劑)

(2).Take 20 PCS PE bag (A3364),put product in bags separately, put 4976-F2XxxTHB-2X20CM-Axx :5 PCS in each bag, then put one bag of drying agent, seal the opening of bag, stick certificate of quality designation list on the outside.Write P/N, Product batch number, quality and store list number (as shown in drawing).

取20PCS PE袋 (A3364),每個袋中分別放入成品 4976-F2XxxTHB-2X20CM-Axx 5 PCS, 然後將袋子中各放一 袋干燥劑, 再把袋口處捏緊,外面貼合格證標示單.分別寫料號,生產批號,數量及入庫單號(如圖所示).

歐品電子(昆山)有限公司

OUPIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)

☒ CONFIDENTIAL ☐ TOP SECRET

SPEC.NO.(規範編號) Q4976SPP-1406

PAGE


3/4

REV.


A

PACKING OPERATION DIAGRAM & INSTRUCTION (包裝作業圖示及說明)

REMARK (備 注)




Drawing One(2)
(圖一(2))



CT-0.5 paper box , lay 20 bags .
(CT-0.5紙盒 , 放20袋)

Drawing One(1)
(圖一(1))



Drawing Two
(圖二)

一.Outer box packing mode:

外箱包裝方式

- (1). Paper box CT- 0.5 Standard 1 PCS,as shown in drawing One(1).
紙箱CT-0.5規格 1 PCS,如圖一(1)所示
 - (2).Put one Air column bag in the upper and lower of the paper box,,2PCS in all,as shown in drawing One(2).
每箱上下各放一塊氣柱袋,共2PCS , 如(圖一(2))所示
 - (3). Put waterproof bag 1 PCS in the paper box.
紙箱內側放入防水袋 1 PCS.
 - (4). Put 20 PCS PE bag filled with finished product in the waterproof bag
于防水袋內放入40袋裝滿成品的PE袋
 - (5).Seal the waterproof bag,then put the Air column bag1PCS on the bag.
if box can not be fulled ,filled with ploy.
(Put 1 PCS Air column bag at the right and left side in the paper box if it is necessary.)
封上防水袋後,放上第二塊氣柱袋,未填滿處用保麗龍填滿.
(必要時,在紙箱的左右兩側各放一塊氣柱袋)
 - (6).Seal the surface of the outer box,as shown in drawing Three.
將外箱上層封口,如(圖二)所示
- The form on the right and flank side of the box must be filled every box gross weight.
外箱之正麥和側麥所要填寫之項目要填寫正確,清晰,每箱之毛重應以實測重量為準

